

MELTON AIR SERVICES

Details

CTAF	121.6
AREA	135.7 MELBOURNE RADAR
WAC	3469, 3470
Status	Unlicensed
Landing Permission	Required
Operator	Melton Air Services
Landing fee	Nil
Runways 04/22	Gravel
Runways 10/28	Grass
Runways 16/34	Grass
Lighting	Runway 04/22
Windsock	Illuminated

Local Traffic Regulations

- Where possible, aircraft should conform to established runway direction.
- Arrivals - At least 3 legs of the circuit to be flown.
- Straight in approaches are not permitted.
- Right Hand Circuits on Runway 04 and 10.
- Landing only on Runway 34.
- Take Off / Landing on Runway 16 not permitted.
- All aircraft to avoid overflying Toolern Vale Township 2 NM NE of aerodrome.
- All aircraft departing (other than touch and go OPS) to commence take off roll from runway end to maximize height over residential areas after take off.

